



Roadranger®

More time on the road™

Bulletin: MDIB-0035

Date: January 24, 2011

Bulletin Type: Service

Topic: ServiceRanger Version 3.2.2.1037 with Database Version 30 released

Issue Description: ServiceRanger software version 3.2.2.1037 with database version 30 has been released.

This ServiceRanger software version has the following enhancements:

- Created new Gen 2 and Gen 3 automated transmission Maximum Start Gear “Dyno-Only” settings to support vehicle dynamometer testing.
- Gen 2 Automated Transmission Model Number configuration changes are now available across all Gen 2 automated product families.
- The Vehicle Fault Count and Vehicle Component Count windows have been removed from the Summary screen to relieve customer misinterpretation concerns.
- Vorad is now displayed as a Bendix Vorad in the “Show All Products” menu tree and the ServiceRanger Help guide.
- The Product Configuration screen and the VPA and Snapshot data can now be viewed at all ServiceRanger user levels.

The Database update includes the following changes:

- Released Gen 3 UltraShift*Plus* Automated Transmission ECU software 5569892
- Released “2010 PACCAR MX Optimized” engine specific shift point configurations for Gen 3 AutoShift, UltraShift and UltraShift*Plus* product families
- Corrected the following MD automated transmission product configurations from being displayed in the Product Configuration screen when connected to HD transmission models:
 - Hill Start Aid
 - Kick Downshift
 - PTO Brake
 - Minimized Downshifts

Containment/Corrective Action:**Affected Models/Population:**

ServiceRanger Version 3.x

Field Strategy:

- The ServiceRanger application with database update can be downloaded from the ServiceRanger web page or by using the Software Manager Update utility. Follow link below to the ServiceRanger web page:

<http://www.roadranger.com/Roadranger/trainingsupport/ServiceRanger/index.htm>

The Software Manager Update utility can be found in the Windows Programs menu. By simply launching the Software Manager utility it should automatically check to see if any updates are available to download. For more information about the Software Manager program reference MDIB0016.

Warranty Information:**Warranty Parts:**

-
-

Warranty Labor:

-
-

Warranty Coverage:

The material contained in this bulletin is product improvement information. Eaton and Dana Corporation are not committed to, or liable for, canvassing existing products. FSUD: 2010-FSUD-1514

Index:

- 1.