



**Subject:** ServiceRanger 4.x Data Content Updates – All

**Document Number:** MDIB0043

**Date:** May 5, 2014

---

**Issue Description:**

This document contains all ServiceRanger 4.x Data Content update information. The most recent version is **1404-02-SCB-2119**. This document has been created as a reference for the information included in each database update.

**Current Release:**

**Data Update 1404-02-SCB-2119**

**Release Date: 4/29/2014**

- Hybrid Transmission Control Module software 5569910 available with all legacy HCM software for all hybrid products.

**Data Update 1403-02-SCB-2099**

**Release Date: 4/2/2014**

- Released 2010/2013 MaxxForce Navistar 13L Optimized MHP/VHP 5572927 Shift Calibration for Gen 3 UltraShift® *PLUS* products
- Released the following shift calibrations for China, Solaris, and Isuzu hybrid products:
  - Isuzu
  - Solaris
  - PBD Diesel
  - PBD CNG Low

**Data Update 1401-01-SCB-2087**

**Release Date: 1/31/2014**

- Released the following shift calibrations for Gen 3 UltraShift *PLUS* products:
  - 2013 MX MHP/VHP Optimized 5572925
  - 2013 MX LAS/VAS Optimized 5573236
- Released Hybrid Control Module software 5500690 for Solaris hybrid product.
- Released Hybrid Control Module software 5500691 for Iveco hybrid product.

### **Data Update 1312-01-S-2077**

**Release Date: 1/17/2014**

- Released Gen 3 UltraShift *PLUS* Transmission ECU software 5569917
- Released Hybrid Control Module software 5500689 for all hybrid products where it applies.
- Removed Hybrid Control Module software 5500682

### **Data Update 1311-01-SCB-2067**

**Release Date: 11/20/2013**

This data update brings the ServiceRanger 4 database up-to-date with all the information in the ServiceRanger 3 database. For more information see service bulletin [MDIB0021](#).

#### **Affected Models/Population:**

ServiceRanger Version 4.x Database

#### **Field Strategy:**

ServiceRanger data updates can be downloaded using the Software Manager Update utility.

#### **Warranty Information:**

None

The material contained in this bulletin is product improvement information. Eaton is not committed to, or liable for, canvassing existing products.