



BACKED BY
Roadranger
SUPPORT

Subject: Endurant Transmission 8-Bolt Bottom PTO Information

Document Number: TAIB0868 EN-US

Date: January 29, 2018

Description:

Endurant Transmissions require a new type of PTO, previous models are not compatible.

Chelsea PTOs are available. Please contact the local Chelsea distributor for additional information. Chelsea PTOs use an O-ring seal installed into a groove on the PTO mounting flange and is included with the PTO kit.



Chelsea (O-ring groove)

Muncie PTOs are now available and will begin shipping product the week of January 29, 2018. Please contact the local Muncie distributor for additional information. Muncie PTOs use a seal plate gasket at the PTO mounting flange which is included with the PTO kit.



Muncie (seal plate gasket)

Note: Chelsea and Muncie PTOs do not require shimming due to improved tolerance requirements at the mounting flange surfaces of both the transmission and PTO housing.

Contact PTO supplier directly If additional information is required:

- Chelsea customer support: 1-888-744-8785
- Muncie customer support: 1-800-367-7867

Note: For additional PTO information reference the Eaton PTO Information Guide TRIG2600: [PTO Installation Guide](#)

Affected Models/Population:

- Endurant Transmissions
- 8-Bolt Bottom PTO

Warranty Information:

Informational only, not a transmission product issue.

The material contained in this bulletin is product improvement information. Eaton is not committed to, or liable for, canvassing existing products. FSUD: 2018-FSUD-2567